

Screaming Wheaties (5.10) on John's Jump/Fan in the Needles Eye area of Custer State Park

The repair was done by Jason McNabb, Ron Yahne, and Adam Bergdale on 7/8/11

Screaming Wheaties is a right leaning crack that is reached by climbing a face protected by a single bolt down low. We replaced the ¼ inch button head with a Fixe Triplex bolt. I installed the new bolt and pulled the old bolt, but was unable to patch the hole due to weather issues (hailstorm). I will return and patch the old hole at a later date.

**Previous Hardware:**

¼ inch by 1 inch non-stainless button head bolt and a non-stainless SMC hanger.

**BHCC Stainless Hardware Installed:**

Fixe Triplex Bolt (x1)

Petzl Coeur Hanger (x1)